

a 1/2" nylon line fouled around the shaft and gland seal of her prop.

\* (d) While in the ice East of the Mackenzie, MK1 ROBERTS and ENS NORRIS removed a damaged fairwater from the rudder stock of the STATEN ISLAND.

(e) The depth of these dives was about 10 feet in 29°F water. Two hose aquamaster regulators were used for the most part. One malfunction occurred when ice formed around the second stage causing no flow. The divers buddy breathed to the ice hole with no problems.

(f) No assistance was needed from STATEN ISLAND during the diving operations off Fairway Rock.

(4) Ice demolition. Explosives were loaded aboard the week before departure and unloaded at Bangor before returning to Seattle. There was no use of demolition materials at any time during the patrol.